Test Report

Applicant : Xi'an Furuize Biotechnology Co., Ltd.

Address : No. 11, Tangyan South Road, High-Tech Zone, Xi'an, Shaanxi, China

The following sample(s) and sample information was/were submitted and identified by/on behalf of the client

Sample Name : Menstrual Cup

Sample Model : sport cup

Sample Lot : /

Sample Received Date : Jun 4, 2020

Test Completed Date : Jun 6, 2020

Test Method : Refer to the next page(s).

Test Results : Refer to the next page(s).

Test Requested	Conclusion
RoHS Directive (EU)2015/863 amending Annex II to Direxitive 2011/65/EU–Lead(Pb), Cadmium(Cd), Mercury(Hg), Hexavalent Chromium(CrVI), Polybrominated Biphenyls (PBBs), Polybrominated Biphenyl Ethers(PBDEs), Dibutyl phthalate (DBP), Butyl benzyl phthalate(BBP), Bis-(2-ethylhexyl)phthalate(DEHP), Di-iso-butyl ortho-phthalate(DIBP)	PASS

Reviewed by: Lab Senior Engineer

Authorized Signature: Technology Manager

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

FLION TESTING TECHNOLOGIES
Add :Gangzi Industrial Park,Furong Industrial Area, Xinqiao Village, Shajing Town, Bao'an District, Shenzhen City
Tel : 86-0755-2724 8885 Fax : 86-0755-2746 0090 Http://www.cnftt.com

Pb, Cd, Hg, Cr(VI), PBBs, PBDEs Test Results:

Test Item	Test method/Instrument	MDL (mg/kg)	Result (mg/kg)	Limit (mg/kg)
Lead(Pb)	IEC62321-5:2013/ICP-OES	2	N.D.	1000
Cadmium(Cd)	IEC62321-5:2013/ICP-OES	2	N.D.	100
Mercury(Hg)	IEC62321-4:2013+A1:2017/ICP-OES	2	N.D.	1000
Hexavalent Chromium(CrVI)	IEC62321-7-2:2017 /UV-VIS	8	N.D.	1000
Sum of PBBs	-	-	N.D.	1000
Monobromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Dibromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Tribromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Tetrabromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Pentabromodiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Hexabromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Heptabromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Octabromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Nonabromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Decabromobiphenyl	IEC62321-6:2015 /GC-MS	5	N.D.	--
Sum of PBDEs	-	-	N.D.	1000
Monobromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Dibromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Tribromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Tetrabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Pentabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Hexabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Heptabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Octabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Nonabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--
Decabromobiphenyl ether	IEC62321-6:2015 /GC-MS	5	N.D.	--

Note:
(1) 1 mg/kg = 1 ppm = 0.0001%
(2) N.D. = Not Detected (less than MDL)
(3) MDL = Method Detection Limit
(4) "--" = Not Regulated

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.


Phthalates Test Results:

Test Item	CAS No.	Test Method / Instrument	MDL (%)	Result (%)	Limit (%)
Dibutyl phthalate (DBP)	84-74-2	IEC 62321-8:2017 / GC-MS	0.005	N.D.	0.1
Butyl benzyl phthalate (BBP)	85-68-7	IEC 62321-8:2017 / GC-MS	0.005	N.D.	0.1
Bis-(2-ethylhexyl)phthalate (DEHP)	117-81-7	IEC 62321-8:2017 / GC-MS	0.005	N.D.	0.1
Di-iso-butyl ortho-phthalate (DIBP)	84-69-5	IEC 62321-8:2017 / GC-MS	0.005	N.D.	0.1

Note:
(1) 1 mg/kg = 1 ppm = 0.0001%
(2) N.D. = Not Detected (less than MDL)
(3) MDL = Method Detection Limit
Remark: The above result(s) was/were only given as the informality value and only for reference

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

Testing Flow Chart:



In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

Test Part Description: Menstrual Cup

Sample Photo



Note: The results shown in this report refer only to the sample(s) tested.

* * * * * End of Report * * * * *

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

FLION TESTING TECHNOLOGIES
Add :Gangzi Industrial Park,Furong Industrial Area, Xinqiao Village, Shajing Town, Bao'an District, Shenzhen City
Tel : 86-0755-2724 8885 Fax : 86-0755-2746 0090 Http://www.cnftt.com